## TECHNICAL UNIVERSITY OF MOMBASA

#### **Faculty of Engineering and Technology**

#### DEPARTMENT OF MECHANICAL AND AUTOMOTIVE ENGINEERING

## UNIVERSITY EXAMINATIONS FOR DEGREE IN BACHELOR OF SCIENCE IN MECHANICAL ENGINEERING

## (BSME) Y3-S2

## EMG 2312: METROLOGY

## SPECIAL/SUPPLEMENTARY EXAMINATIONS

#### SERIES: MAY 2016

## TIME: 2 HOURS

#### **INSTRUCTIONS:**

- ♦ You should have; Answer booklet,; Drawing instruments and Scientific calculator
- This paper consists of FIVE questions
- ✤ Attempt any THREE questions.

#### This paper consists of THREE printed pages

**QUESTION 1 (a) (i)** In taking measurements using the gear tooth vernier, derive the expression for gear tooth width and height setting (5 marks)

- (ii) A spur gear of 21 teeth and module 3 is to have its teeth measured using the gear tooth vernier. Evaluate the vernier width and height setting (5 marks)
- b) (i)For a spur gear using the gear tooth vernier derive the expression for gear tooth width and height setting for the constant chord method (5 marks)
- (ii) A spur gear of 22 teeth and module 4 is to have its teeth measured by the constant chord method. Determine the vernier width and height setting (5 marks)

#### **QUESTION 2**

Sample	Measurements per sample						
No	Hundredths of one mm.						
1	622	623	622	624	623		
2	623	624	625	623	624		
3	624	623	625	623	624		
4	624	624	625	625	626		
5	624	624	625	625	626		
6	624	625	626	624	625		
7	625	625	626	626	625		
8	626	625	625	625	627		
9	626	626	627	626	626		
10	626	627	627	628	626		

The table shows samples of five taken at regular intervals from a process; 10 samples in all being taken. Plot the  $\overline{x}$  and w-charts.

#### **QUESTION3**

- a) Describe the main requirements of the sine bar. (5 marks)
- b) Figure Q3b shows a gauge made in the geometrical profile shown. Determine the dimension h to the nearest 0.002mm. On such a gauge the dimension h is found to be correct; but each of the 120° angles is found to be four minutes of arc undersize. Determine the error introduced into the dimension 1 to the nearest 0.002mm. (10 marks)
- c) Figure Q3c shows a method used to determine large radius of curvature by measuring dimension h. If the dimension h=32.49mm, determine the radius of curvature R. *(5 marks)*

#### **QUESTION4**

- a) With respect to testing of screw threads, derive the expression for:
  - (i) Best wire size
  - (ii) Simple effective diameter. (11 marks)
- b) On testing a given thread of flank angle 30° and pitch 3mm, the wire available was of diameter 2mm and resulted in the dimension T under the wires of 49.132mm. Determine:
  - i) Best wire size
  - ii) Simple effective diameter. (4 marks)
- c) Determine the diameter of a large bore measured with a pin gauge of length 450mm that rocks for 37mm. (5 marks)

#### **QUESTION5**

 a) (i) Derive from first principles the Dmax and Dmin expressions for the taper plug gauge shown (Fig Q5)

(ii)On such a taper plug gauge the roller diameter is 10mm, h=53mm, H=68mm,  $M_2=49.27$ mm,  $M_1=41.04$ mm and S=6mm. Determine:

- (I) Taper angle
- (II) D<sub>s</sub>
- (III) D<sub>min</sub>
- (IV) D<sub>max</sub> (14 marks)
- b) The M87 set of slip gauges has the following pieces (Table Q5)

Range (mm)	Steps (mm)	No. of pieces
Wear blocks 2.5	-	2
1.001 to 1.009	0.001	9
1.01 to 1.49	0.01	49
0.5 to 9.5	0.5	19
10 to 90	10	9
1.0005	-	1







## FACTORS USED IN $\bar{x}$ CHARTS

.

Sample size n	Warning factor A <sup>1</sup> 0.025	Action factor $A^{1}_{0.001}$	
2	1.229	1-937	
3	0.668	1.054	
4	0.476	0.750	
5	0.377	0.594	
6	0.316	0.498	
0	0.274	0.432	
9	0.244	0.384	
0	0.220	0.347	
10	0.202	0.317	

# FACTORS USED IN w CHARTS

Sample size n	Upper action factor D <sup>1</sup> 0.999	Upper warning factor D <sup>1</sup> 0.975	Lower warning factor D <sup>1</sup> 0.025	Lower action factor D <sup>1</sup> 0-001
2 3 4 5 6 7 . 8 9 10	4.12 2.98 2.57 2.34 2.21 2.11 2.04 1.99 1.93	2.81 2.17 1.93 1.81 1.72 1.66 1.62 1.58 1.56	0.04 0.18 0.29 0.37 0.42 0.46 0.50 0.52 0.54	0.00 0.04 0.10 0.16 0.21 0.26 0.29 0.32 0.35
			FIG Q2	60

ŕ

• .